2018-19

THIRD PARTY INSPECTION REPORT

Name of the Client : **Executive Engineer,**
Electrical- Yelahanka Division,
BBMP, Bangalore.

Name of Agency : **Executive Engineer-1,**
KRIDL, Bangalore.

Name of the Work : Providing Street Lights in Ward No.08 , BBMP, Bangalore.

Estimated Cost - Rs. 25.00 Lakhs

THIRD PARTY INSPECTION CONSULTANTS

CIVIL QUALITY CONSULTANTS AND ENGINEERS
NABL Accredited as per ISO/IEC: 17025-2005 Laboratory
An ISO 9001 2008 Certified Company

#133, Bhuvaneshwarinagar, Dodda Basti Main Road, Bangalore-560056
e-mail: civilqualityconsultants@gmail.com Ph: 8553518550/9886998316

"TheRoadtoSuccessisalwaysunderConstruction"

CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)
An ISO 9001: 2015 Certified Company
NABL Accredited As Per ISO/IEC : 17025:2005 Laboratory

JAS-ANZ
ISO 9001:2000 CERTIFIED

Name of Work : **Providing Street Lights in Ward No.08 , BBMP, Bangalore.**

Contractor/Agency	:	**Executive Engineer**, KRIDL, Bangalore.
Name of Client	:	**Executive Engineer,** Electrical-Yelahanka Division, BBMP, Bangalore.
Total Bill Cost in Lakhs	:	Rs.24,99 Lakhs
Date Of Inspection	:	30.09.2018
Status of Bill	:	First & Final Bill
In the Presence of	:	(a) **Mr. Rajendra Nayak(Assitant Executive Engineer-1, Electrical Yelahanka Zone),** BBMP, Bangalore.
	:	(b) **Mr. kumar,** (Electrical Engineer) M/s Civil Quality Consultants & Engineers, Bangalore.

3rd Party Compliance Report

SL No	Description of the Item	Unit	Quantity	Comments / observations
1	LED Street light, Supply of LED Street light with Pressure die cast aluminum housing body with optimal heat sink for better thermal dissipation.....	Nos	70	Supplied Material Quality found satisfactory
2	Supplying and fixing....mm dia class A GI pipe bracket up to 2 meters long..... Using 32mm	Nos	60	Supplied Material Quality found satisfactory
3	Wiring for lighting/power circuit using one of PVC insulated 1100v grade stranded .....System of wiring a)4sqmm	Mtr	275	Supplied Material Quality found satisfactory
4	Fixing halogen/metal hallide/SVL/IL/LED flood lights fittings over existing pole/wall ceiling including clamps bolts.....	Mtr	48	Supplied Material Quality found satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Verified By

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Authorised Signatory

Authorised Signatory

Office & Laboratory : # 133, Bhuvaneshwarinagar, Dodda Basti Main Road, Bangalore - 560 056.
e-mail:civilqualityconsultants@gmail.com Ph: 080-23240644 / Mob: 8553518550

CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)
An ISO 9001: 2015 Certified Company
NABL Accredited As Per ISO/IEC : 17025:2005 Laboratory

JAS-ANZ
ISO 9001:2000 CERTIFIED

NO: CQCE/3rd Party/Yelahanka Division/1/ 2018-19 Date: 01.10.2018

To,
Executive Engineer,
Elctrical – Yelahanka Division
BBMP, Bangalore.

Sir

Sub:- Submission of 3rd Party Report for the work of Providing Street Lights in Ward No.08 , BBMP, Bangalore...- reg.

Ref:-

(i)**Job code No**. 008-17-000061
(ii)EE(Elec)/YZ/WO/000017/2018-19 Dated:-20/08/2018

Adverting to the above, we would like to submit the 3rd Party Inspection Report for the above said work in Electrical –Yelahanka Division along with Mr. Rajendra Nayak (Assistant Executive Engineer-1, Electrical Yelahanka Zone), and Mr. Kumar (Electrtical Engineer, 3rd Party Consultants), Bangalore on 30.09.2018

The following works inspected the details of works inspected is as follows,

Sl no	Name of the work	Amount of estimate Rs in Lakhs.	Remarks
1	Providing Street Lights in Ward No.08 , BBMP, Bangalore.	Rs. 25.00 Lakhs (1st and Final bill)	Work carried out satisfactorily Details mentioned in 3rd party compliance report

For details of works and measurements checked during the inspection time in the presence if the officials /officers afore said.

This is for favor of kind information and needful in the matter.

Enclosures: 3rd part Inspection report
Thanking you

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

yours faithfully
Authorized signatory

Office & Laboratory : # 133, Bhuvaneshwarinagar, Dodda Basti Main Road, Bangalore - 560 056.
e-mail:civilqualityconsultants@gmail.com Ph: 080-23240644 / Mob: 8553518550

Providing Street Lights in Ward No.08 , BBMP, Bangalore.

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore

Providing Street Lights in Ward No.08 , BBMP, Bangalore.

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore